Product Safety Recall

Radio-controlled Electric 2WD Hobby Cars 1:10 Scale ECX Desert Buggy, ECX Monster Truck, ECX Brutus and Slipper Pad Spare Parts



Supplied nationally through hobby stores 1 June 2016 - 11 June 2021

Defect: The slipper pads in these vehicles contain chrysotile asbestos. Asbestos fibres may be released from the slipper pad in the vehicle through friction and users may be exposed to asbestos fibres if the vehicle is disassembled for repair or maintenance.

Hazard: If asbestos fibres are released into the air and breathed in, they can cause serious medical conditions, including asbestosis, lung cancer and mesothelioma.

What to do: Owners of affected vehicles must not open their vehicles. Affected vehicles should be returned to their place of purchase for repair. If your vehicle was bought second-hand, your place of purchase is no longer in business or you do not remember where you purchased the vehicle, contact OMP for further instructions.

Contact details: Phone (08) 8186 0899 (Monday to Friday, 9am - 5pm CST), complete the form available at https://www.omp.com.au/contact or email customerservice@omp.com.au

See productsafety.gov.au for Australian product recall information